

2230Z 27 DEC 60

S E C R E T

25X1A

DIRECTOR

[REDACTED]

ROANTON

DPD (1,2,3,4,5,6,7,8,9,10)

ROUTINE

S/C (11)

25X1A DHD

TOR: 2303Z 27 DEC 60

IN 40612

[REDACTED]

0976

REF: [REDACTED] 5888 (OUT 78366)

25X1A

25X1A

1. PER PARA 4 REF MSG REQUEST BAIRD TECH REP REPORT LAC
5 JANUARY 1961 FOR SEXTANT SUPPORT AIRPLANE 351. LAC SUPPORT
NEED WILL BE FOR APPROXIMATELY ONE WEEK.

25X1A

2. REQUEST [REDACTED] INITIATE ACTION TO PROVIDE TECH REP FOR
DRIFTSIGHT SUPPORT. THIS INDIVIDUAL ALSO TO REPORT LAC
5 JANUARY 1961.

25X1A 3. IF FLIGHT TESTS SHOW AUTOPILOT SUPPORT IS REQUIRED LAC
WILL CONTACT LOCAL [REDACTED] REPRESENTATIVES, [REDACTED]
FOR TECHNICAL ASSISTANCE.

25X1A

END OF MESSAGE

ECP-LAC 103

2/12/81

O₂₀₁₁ ILLEGIB

[REDACTED]